

**M 5.4, Timor region, Indonesia**

Origin Time: 2023-08-31 10:29:29 UTC (Thu 18:29:29 local)  
Location: 9.5312° S 123.8598° E Depth: 54.6 km



**PAGER**  
**Version 2**

Created: 2 hours, 2 minutes after earthquake

**Estimated Fatalities**

Green alert for shaking-related fatalities and economic losses. There is a low likelihood of casualties and damage.

**Estimated Economic Losses**




**Estimated Population Exposed to Earthquake Shaking**

ESTIMATED POPULATION EXPOSURE (k=x1000)		—*	2,620k	1,531k	0	0	0	0	0	0
ESTIMATED MODIFIED MERCALLI INTENSITY		I	II-III	IV	V	VI	VII	VIII	IX	X+
PERCEIVED SHAKING		Not felt	Weak	Light	Moderate	Strong	Very Strong	Severe	Violent	Extreme
POTENTIAL DAMAGE	Resistant Structures	None	None	None	V. Light	Light	Moderate	Mod./Heavy	Heavy	V. Heavy
	Vulnerable Structures	None	None	None	Light	Moderate	Mod./Heavy	Heavy	V. Heavy	V. Heavy

\*Estimated exposure only includes population within the map area.

**Population Exposure**



**Structures**

Overall, the population in this region resides in structures that are vulnerable to earthquake shaking, though resistant structures exist. The predominant vulnerable building types are unreinforced brick with concrete floor and precast concrete frame with wall construction.

**Historical Earthquakes**

Date (UTC)	Dist. (km)	Mag.	Max MMI(#)	Shaking Deaths
1995-05-21	170	5.2	VII(70k)	1
1977-08-27	223	7.0	VIII(1k)	2
1987-11-26	144	6.5	VIII(6k)	37

Recent earthquakes in this area have caused secondary hazards such as landslides that might have contributed to losses.

**Selected City Exposure**

from GeoNames.org

MMI	City	Population
IV	Naisano Dua	2k
IV	Taen Tengah	<1k
IV	Kasmabaki	<1k
IV	Oelbanu	<1k
IV	Letkole	<1k
IV	Nefoneut	<1k
IV	Kupang	282k
III	Suai	22k
III	Maliana	22k
III	Same	25k
III	Dili	150k